


Lecture 5: Heat Treatment of Steel

MMat 380

Lecture outline

- TTT diagrams (hypo and hyper eutectoid steels)
- CCT vs TTT diagrams
- Austenizing Heat Treatments
 - For **hypo**eutectoid – mild steels
 - For **hyper**eutectoid steels
- Other Heat Treatments (no austenizing)
- Stress Relief

Hypoeutectoid steel (non-equilibrium transformation)




Phase diagram

eutectoid

Hypoeutectoid

3

Hypoeutectoid and eutectoid steels



Hypoeutectoid

Eutectoid

4

Hypoeutectoid steels (<0.8%C)

- As we decrease the transformation T in 0.5%C steel then:
 - Decrease amount of proeutectoid ferrite and increase amount of pearlite
 - Decrease proeutectoid ferrite grain size – increase strength (Hall-Petch equation)

$$\sigma_y = \sigma_o + kd^{-1/2}$$

- Decrease spacing of pearlite

5

Hypoeutectoid steels

- Fe₃C nucleates P transformation
- Shift in eutectoid composition with lower transformation temp
 - Can get 100% pearlite in 0.4%C steel


6

Hypoeutectoid steels

- As transformation T decreases
 - increase pearlite and decrease proeutectoid ferrite (ratio of $\alpha/\text{Fe}_3\text{C}$ in pearlite increases)
 - Finer pearlite
 - Finer grain size for proeutectoid ferrite
 - Change in eutectoid composition
 - Change in A_3 and A_1

7

Hypereutectoid and eutectoid steels




Hypereutectoid

Eutectoid

8

TTT to CCT curve




9

CCT vs TTT diagram

- Transformation curve pushed **down** and to the **right**
 - (i.e. lower temperature and increased time)
- Pre-transformation thermal force required is constant
 - i.e. isothermal @ 650°C – 6 seconds
 - = 723-625°C – continuous in 8 seconds


10

CCT diagram (eutectoid steel)



11


CCT diagram (1030 steel)



12


Microstructure (1030 steel)

F+P




a) DPH 139

F+P




b) DPH 170


F+P




c) DPH 217



d) DPH 336
F+P+B+M




e) DPH 415
F+P+B+M




f) DPH 481
P+B+M

ANALYSIS Wt% (See note on page 8)

C	Si	Mn	P	S	Cr	Mo	Ni	Al	Nb	V
0.18	0.20	0.45	0.020	0.020	-	-	-	-	-	-



CCT diagram



Heat treatment of steel

- Heat to γ and **austenitize** – control cool

Hardening	quench to martensite and temper
Martempering	quench to above M_s and equilibrate cool to martensite and temper
Austempering	quench to above M_s and hold to bainite
Normalize	air cool (@ ~5-10°C/min) - α & pearlite
Full anneal	furnace cool (@~1°C/min) - α & pearlite

15


Heat treatment of steel

2. Heat to temperatures $< 723^\circ\text{C}$

Spheroidize	softening (Fe_3C spheroidizes - free machining steels)
Process Anneal	recrystallize ferrite (low %C steel)
Stress relief	usually low %C structurals

16

Heat Treatments




17

Martempering

- Modified quenching procedure used to minimize distortion/residual stresses of heat treated material and decrease cracking
 - Austenitize the steel
 - Quench it in hot oil/molten salt to a T slightly above/below M_s
 - Hold it in the quench medium until T uniform throughout the steel
 - Cool at a moderate rate to prevent drastic T differences between the surface and centre of the steel

18

Martempering



19

Martempering effects

Heat treatment	R_c	Impact (ft-lb)
Water quench and temper	53.0	12
Martemper and temper	53.0	28

20

Austempering

- Produces: **bainitic structure in plain-carbon steel**
 - Austenitize the steel
 - Quench into a hot salt bath @ a temp slightly above M_s held isothermally
 - Cooled to room temperature **in air**


21

Austempering

- Produces: **bainitic structure in plain-carbon steel**
 - Austenitize the steel
 - Quench into a hot salt bath @ a temp slightly above M_s held isothermally
 - Cooled to room temperature **in air**

22

Austempering



23

Austempering

- **Advantages over conventional Q+T**
 - Improved ductility and impact strength for a given hardness
 - Decrease cracking and distortion quenching
- **Limitations for plain carbon steels**
 - Relatively thin sections (i.e. 3/8" max) – lawn mower blades; good shovels

24

Normalizing/Annealing

- Normalizing - $\sim 5\text{-}10^\circ\text{C}/\text{min}$
- Annealing - $\sim 1^\circ\text{C}/\text{min}$
- Reasons for normalizing (castings/plate etc.)
 1. Refine grain size
 - increase strength
 - increase toughness
 - decrease d-b transition temperature
- eg: pressure vessels, ship plate, pipelines, digesters etc.

25

Normalizing/Annealing

2. Redistribute solute in castings etc.


- high temperature diffusion

Reasons for annealing:

- Fully soften material
- Put it in its most ductile state

26

Microstructure



- Annealed (1°C/min)
 - Yield pt: 250 MPa
 - % elongation/2 in: 37

- Normalized (10°C/min)
 - Yield pt: 310 MPa
 - % elongation/2 in: 35

27


Mechanical properties

Normalized structures are stronger because:

- Finer pearlite
- More pearlite
- Finer α grain size

28

Example: I-beam



- low %C structural (0.2%C)
- Cooling rate to α & pearlite important for strength
 - Web - **thin** cools **first** from rolling temp.
 - Flange - **thick** cools **slowly** from rolling temp.

Therefore

- Flange has lower σ_y than web
- Code requires specification from web (strongest)
 - (i.e. 370 MPa Y.S)
- Flange is higher stressed but **may** have lower strength


29

Normalizing/Annealing of hypereutectoid steel

- **Normalizing**
 - $\sim 5\text{-}10^\circ\text{C}/\text{min}$
 - extensive grain boundary network of proeutectoid Fe_3C
 - **Annealing**
 - $\sim 1^\circ\text{C}/\text{min}$
 - **no** extensive grain boundary network of proeutectoid Fe_3C
- for C contents $>0.8\%$:
- % elongation values of normalized structure \ll annealed

30

Heat Treatments



31

Heat treatments of steel

- Heat to temp $< 723^{\circ}\text{C}$ (no austenizing)
 - [Spheroidize](#) (Fe_3C spheroidizes – free machining steels)
 - softening
 - [Process anneal](#)
 - Recrystallize ferrite (low %C steel)
 - [Stress relief](#)
 - Usually low %C structurals

32

Spherodizing

- 24 hrs @ temp just under A_1
 - carbides will spherodize if held for long time < 723°C
 - softens and puts steel in free machining condition
- sometimes buy steel in spherodized condition for good dimensioning on machining and then heat treat later

33

Process anneal

- 1 hr @ $600\text{-}650^\circ\text{C}$ (no austenizing)
- Recrystallizes cold worked ferrite
- Y.S and UTS drastically reduced
- Sometimes used to selectively treat localized cold worked areas
- used in production of steel wire, nails etc.

34

Stress relief

- Up to 678°C (times up to 24 hrs; thermal blankets)
- Done to relieve residual stresses
 - @ hi temp dislocations rearrange to relieve stresses (easier mobility @ high T – lower YS)
 - After cooling residual stress is reduced
- Less chance of fatigue, stress corrosion etc.
- Digestors and other pressure vessels have to be stress relieved to remove residual stresses associated with welds


35

Internal residual stresses

- May develop because of:
 - **Plastic deformation** processes such as machining or grinding
 - **Non-uniform cooling** of a piece that was produced or fabricated at an elevated temperature
 - **Phase transformation** induced upon cooling; parent and product phases have different densities


36

Dilation curve for martensite formation




37

Typical residual stresses




38

Through hardening



39

Shallow hardening



40