

# Lecture 11: Stainless Steels

Mmat 380

## Topics to be covered


- Passive surface oxide layer and Cr
- Purpose of Ni addition
- Susceptibilities (failure mechanisms)
- Other alloying elements and their purposes
- Production of stainless steel: 6 types

## Passive surface oxide layer and Cr


- Based on formation of  $\text{Cr}_2\text{O}_3$ 
  - Similar to other fairly reactive metals: Ti, Al
- Can put Fe into passive region on Eh/pH and form protective Fe oxide surface layer: anodic protection
  - Need oxidizing atmosphere to **maintain** the protective layer
  - reducing agents will destroy film and cause corrosion same as C-steel

3

## Pourbaix diagrams: brief introduction






4



## Pourbaix diagrams – 3 regions

- 1) **The corrosive region:** the most stable form is the metal cation or any non protective anion corrosion will occur until the metal is consumed
- 2) **The immune region:** corrosion is thermodynamically impossible
- 3) **The passive region:** an insoluble protective layer (hydroxide or oxide layer) is the most stable form; initial corrosion will occur until a protective layer is formed






9

## Cr in steel

- Minimum of 12% Cr required for **passive layer**: the more Cr the better
  - Is stainless steel if :  $12 > \%Cr > 30$
  - Most common :  $16 > \%Cr > 22$
- If too high: can get brittle  $\sigma$  phase formation

10


## Polarisation curves: brief introduction



**Fig. 14** Polarization curve for a metal/metal ion system that undergoes an active to passive transition

11


## Minimum 12%: Anodic Polarisation Curves



**Fig. 8** Schematic anodic polarization diagrams for stainless steels containing various amounts of chromium. (1) 3% Cr; (2) 10% Cr; (3) 14% Cr. The polarization curve for the cathodic reaction  $O + ne^- \rightarrow R$  is also shown. Arrows indicate the effect of chromium addition on  $i_{crit}$ ,  $E_{pass}$ ,  $i_{pass}$ , and  $i_{trans}$ .

12


## Maximum 30%: Sigma formation on Fe-Cr phase diagram




13

## Precipitation of Sigma phase ( $\sigma$ -phase) in ferrite matrix

- Fe- 27%Cr ferritic stainless steels heated for 131 days @ 565°C




200x



1000x

14

## Corrosion rate vs wt% Cr



15

## Purpose of Ni addition

- up to 25% Ni added
- More formable austenitic FCC phase instead of BCC formed
  - Only minor corrosion/oxidation resistance increase

16



# Nickel Pourbaix Diagram





FIG. 1. Potential-pH equilibrium diagram for the system nickel-water, at 25°C.

# Overlay of Ni and Fe Pourbaix diagrams



## Susceptibilities (failure mechanisms)

- Pitting: pitting resistance index
- Crevice corrosion
- Intergranular corrosion – weld decay
- Stress corrosion cracking

Note:

SS not always better than C-steel as can get selective attack/cracking,

Localized attack of passive layer can be catastrophic.

Main culprit:  $\text{Cl}^-$  so beware of proper grade selection for coastal regions.

19

## 1. Pitting

- Passive layer attacked locally
  - $\text{Cl}^-$  ion and others
- Deep localized corrosion

Increased tendency with:      Decreased tendency with:


- |                            |                  |
|----------------------------|------------------|
| • Increasing $\text{Cl}^-$ | • Increasing %Cr |
| • Increasing T             | • Increasing %Mo |
| • Decreasing pH            | • Increasing %N  |
| • (increasing acidity)     |                  |

20

# 1. Pitting

- Pitting Resistance Index


$$PRE = \%Cr + 3.3\%Mo + 18\%N$$




21

## Examples of Pits

Pitting in centrifuge  
exposed to  $CaCl_2$



Deep pits



Shallow pits

22


## 2. Crevice Corrosion

- Similar to pitting (area with high local conc.)
- Oxygen cells:
  - Low [O] areas corrode: anodic
  - High [O] areas protected: cathodic
    - Note:
      - anodic rxn: oxidation: production of  $e^-$
      - Cathodic rx: reduction: consumption of  $e^-$
  - Bolted connections susceptible,
  - under dirt, scale etc.

Want: open shallow crevices: continued entry of bulk environment, weld overlay with more corrosion-resistant alloy in some cases or cathodic protection

23

## Examples of Crevice Corrosion



Crevice-related corrosion for different alloys in natural seawater. (a) Alloy 904L (20Cr-25Ni-4.5Mo-1.5Cu) after 30 days. (b) 70Cu-30Ni after 180 days. (c) Alloy 400 (70Ni-30Cu) after 45 days

24



## Factors that can affect the crevice corrosion resistance of stainless steels

geometrical	Metallurgical	Environmental	Electrochemical reactions
Type of crevice: metal to metal nonmetal to metal Crevice gap (tightness) Crevice depth Exterior to interior surface area ratio	Alloy composition: major elements minor elements impurities Passive film characteristics	Bulk solution: O <sub>2</sub> content pH chloride level temperature agitation Mass transport, migration Diffusion and convection Crevice solution: hydrolysis equilibria Biological influences	Metal dissolution O <sub>2</sub> reduction H <sub>2</sub> evolution

25


### 3. Intergranular corrosion

- If held 400-850°C region: CrC ppt occurs on grain boundaries: Cr<sub>23</sub>C<sub>6</sub>
- Depletes adjacent areas of Cr
- Grain boundary corrodes
  - Also referred to as **Weld decay** and **Sensitization**







26

# Corrosion rate vs wt% Cr




27

## Chromium carbides at grain boundaries




## Weld Segment: sensitization/weld decay



29


## Polarisation curves: brief introduction



**Fig. 14** Polarization curve for a metal/metal ion system that undergoes an active to passive transition

30

## Anodic polarization in sensitized alloy



Higher current; more corrosion, in depleted zone

**Fig. 1** Anodic polarization behavior of an active-passive alloy with grain-boundary depleted zones (schematic)

31

## 3. Intergranular corrosion

Decrease by:


- increasing %Cr
- Stabilizing by adding Ti or Nb/Ta (stronger carbide formers)
- Decreasing %C
- Heat treat to 1050°C to redissolve carbides and quench through sensitized temperature region

32



## 4. Stress corrosion cracking

- Branched
- Stress (residual or applied)
- Contain ionic species
- $\text{Cl}^-$  and  $\text{OH}^-$  for stainless steel



33

## Other alloying elements and their purposes

Element	Amount (%)	Purpose
Cr	12-30	$\text{Cr}_2\text{O}_3$ – gives stainless character, stabilises $\alpha$ phase
Ni	0-25	Stabilises $\gamma$ phase (FCC)
Mo	0-9	Reduces pitting and crevice corrosion; stabilises $\gamma$ -phase
N	<0.5	Reduces pitting/crevice corrosion; stabilizes $\gamma$ -phase
Ti, Nb	<1	Strong carbide formers; reduce sensitization
C	<0.15 except martensitic grades	Hard martensite for cutting edges; stabilizes $\gamma$ -phase
Mn	0-12	Ni replacement; stabilizes $\gamma$ -phase

34

## Production of Stainless Steels

<b>Types</b>	<b>Major Alloy Additions</b>	<b>AISI</b>
• Ferritic - $\alpha$	Fe-Cr	4xx
• Martensitic	Fe-Cr-C	4xx
• Austenitic - $\gamma$	Fe-Ni-Cr	3xx
• Duplex ( $\alpha+\gamma$ )	Fe-Cr-Ni	
• Precipitation hardened	Fe-Cr-Ni	
• Super ferrites & austenitics	Higher alloy versions of 1 & 3	