

บทคัดย่อ

จากการศึกษาเรื่อง การเพิ่มประสิทธิภาพเครื่องปั้นดินเผา นั้น พบปัญหาสำคัญในการผลิตเครื่องปั้นดินเผาในการประกอบธุรกิจชุมชน ได้แก่ ด้านระยะทางในการผลิต การวางผังโรงงาน การใช้เวลาที่ยาวเกินไปในการผลิต ซึ่งทางของกลุ่มเราได้มีแนวทางการแก้ไขโดยการพัฒนากระบวนการผลิตใหม่เพื่อให้ในการผลิตมีกระบวนการผลิตนั้นเป็นระบบและใช้เวลาในการผลิตที่น้อยลงอีกทั้งให้ระยะทางในการผลิตสั้นลงกว่าเดิมพร้อมทั้งขอความร่วมมือจากชุมชนเพื่อให้การปรับปรุงครั้งนี้เป็นไปตามวัตถุประสงค์ที่วางไว้ถึงจะบรรลุในแต่ละข้อของวัตถุประสงค์นั้น

ABSTRACT

From the study. Optimizing the pottery. Found significant problems in the production of pottery in the business community, including the distance in manufacturing The plant layout. Excessive time spent in production. Which the group we have solutions to the problems by developing new manufacturing processes for the production process, the system and take time to produce less as well as the distance to produce shorter, more along with ask for cooperation from the community to make this update is based on the objectives to be achieved in the blank, each of the objectives.